

v3.1.6 [2017-01-17]

1. fix some spelling mistake
2. improve the radio signal strength bar

v3.1.7 [2017-01-17]

1. fix some spelling mistake

v3.1.8 [2017-01-17]

1. improve the method of the waypoint saving

v3.1.8 [2017-01-23]

1. update bootloader to v1.4

v3.2.1 [2017-01-25]

1. fixed the problem of [Down] key

v3.2.3 [2017-02-28]

1. fixed the bug when saving waypoint, always warning "GPS Signal Low."
2. user could set home position without SD card
4. don't show the compass when not in auto-pilot mode, avoid confusing with compass of tf640
5. fixed the bug: after exit menu, the main-screen maybe lost left half side
6. before start autopilot, add a message box to show the distance from current position
7. add a SD logo when there is a sd card inside the display

v3.2.4 [2017-03-08]

1. fix some spelling mistake
2. notice user to set joystick to middle point before start autopilot

v3.2.6 [2017-03-24]

1. fixed the bug of south hemisphere, and also need to update ccu to ver3.43
2. improve the message box of start autopilot

v3.2.7 [10:24 2017/4/11]

add message-box to notice CCU need update to fix south hemisphere bug

v3.2.8 [2017-04-18]

1. change max range limit to 500m

v3.3.1 [2017-04-21]

1. Add Russian menu
2. fix bug of menu

v3.3.2 [8:59 2017/4/28]
fix bug of menu translate

v3.3.3 [17:20 2017/4/28]
fix bug of menu translate

v3.3.4 [16:23 2017/5/5]
1. fix bug of menu strings
2. add function of del Home position
3. fix the bug of save waypoint with short-cut key

v3.3.5 [19:36 2017/5/7]
1. fixed the bug when coordinate between -1.00° ~ $+1.00^{\circ}$ degree

v3.3.6 [14:25 2017/5/8]
1. change Russian menu

v3.3.7 [2017-05-09]
1. nothing changed

v3.3.8 [15:28 2017/5/14]
1. improve the process of detecting number of fixed satellites
2. TDSP_Vx.xxT_yymmdd is for new screen, before update the display, must check the pre-verion in menu [System Info.]
3. DSP_Vx.xx_yymmdd is for old screen, before update the display, must check the pre-verion in menu [System Info.]