

## ReleasenoteofXPilotdisplay

v3.1.6 [2017-01-17]

1. fix some spelling mistake
  2. improve the radio signal strength bar
- 

v3.1.7 [2017-01-17]

1. fix some spelling mistake
- 

v3.1.8 [2017-01-17]

1. improve the method of the waypoint saving
- 

v3.1.8 [2017-01-23]

1. update bootloader to v1.4
- 

v3.2.1 [2017-01-25]

1. fixed the problem of [Down] key
- 

v3.2.3 [2017-02-28]

1. fixed the bug when saving waypoint, always warning "GPS Signal Low."
  2. user could set home position without SD card
  4. don't show the compass when not in auto-pilot mode, avoid confusing with compass of tf640
  5. fixed the bug: after exit menu, the main-screen maybe lost left half side
  6. before start autopilot, add a message box to show the distance from current position
  7. add a SD logo when there is a sd card inside the display
- 

v3.2.4 [2017-03-08]

1. fix some spelling mistake
  2. notice user to set joystick to middle point before start autopilot
- 

v3.2.6 [2017-03-24]

1. fixed the bug of south hemisphere, and also need to update ccu to ver3.43
2. improve the message box of start autopilot

v3.2.7 [10:24 2017/4/11]

add message-box to notice CCU need update to fix south hemisphere bug

---

v3.2.8 [2017-04-18]

1. change max range limit to 500m
- 

v3.3.1 [2017-04-21]

1. Add Russian menu
  2. fix bug of menu
- 

v3.3.2 [8:59 2017/4/28]

fix bug of menu translate

---

v3.3.3 [17:20 2017/4/28]

## ReleasenoteofXPilotdisplay

fix bug of menu translate

---

v3.3.4 [16:23 2017/5/5]

1. fix bug of menu strings
  2. add function of del Home position
  3. fix the bug of save waypoint with short-cut key
- 

v3.3.5 [19:36 2017/5/7]

1. fixed the bug when coordinate between -1.00~+1.00 degree
- 

v3.3.6 [14:25 2017/5/8]

1. change Russian menu
- 

v3.3.7 [2017-05-09]

1. nothing changed
- 

v3.3.8 [15:28 2017/5/14]

1. improve the process of detecting number of fixed satellites
2. TDSP\_Vx.xxT\_yymmdd is for new screen, before update the display, must check the pre-verion in menu

[System Info.]

3. DSP\_Vx.xx\_yymmdd is for old screen, before update the display, must check the pre-verion in menu

[System Info.]

---

[v3.3.6 ~ v3.5.2] internal version

---

v3.5.3 [2017/10/1`]

1. add menu [Steering Sens.] for different boats, small and quick steering boat need to be parmeter 1~4, big and slow boat need to be 6~10. default setting is 5 for most of the boat in the market.

To active this function, need to update the software of CCU to v3.51 or later.

2. remove the Target 1~3 from working screen. all 500 waypoints can be set as target by press [Navi] button as shortcut.

3. allow user to rename the waypoint. Press [Enter] key to enter [waypoint] management menu, move cursor to the waypoint, press [Enter] key, then select menu[Rename]